

Two 2dvds down

Submitted by Patrick.Gatlin on Sat, 2013-04-27 22:38

Date:

Saturday, April 27, 2013 - 22:30

Instrument List:

- [Red](#)

Discussion:

2dvd sn70 and 37 were calibrated today. However calibration of sn38 was not possible due to the problem explained below.

2dvd sn38 and sn37 are not collecting data due to issues with camera communications. A few more things will be tried to resolve the problem with sn37, but we have asked the manufacturer to logon remotely to sn38 to help troubleshoot.

The plan is to calibrate sn35 and 36 and hopefully resolve the sn37 problem tomorrow.

PG
